

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	285	606/113,114,127,200.cc ls. and (guidewire or (guide adj wire) or core) and filter	USP AT	2004/09/2 9 13:24			0
2	BRS	L2	308	606/113,114,127,200.cc ls. and (guidewire or (guide adj wire) or core or guide) and filter	USP AT	2004/09/2 9 13:25			0
3	BRS	L3	297	2 and (shaft or tub\$5 or sleeve or sheath)	USP AT	2004/09/2 9 13:26			0
4	BRS	L4	101	3 and actuat\$4	USP AT	2004/09/2 9 13:41			0
5	BRS	L5	69	3 and link\$4	USP AT	2004/09/2 9 13:36			0
6	BRS	L6	29	5 not 4	USP AT	2004/09/2 9 13:36			0
7	BRS	L7	5	("4779628"   "5695519"   "5769816"   "5779716"   "5928261").PN.	USP AT	2004/09/2 9 13:39			0
8	BRS	L8	4	6187025.URPN.	USP AT	2004/09/2 9 13:39			0
9	BRS	L9	32	("20010041908"   "35540 50"   "3996938"   "430040 8"   "4650466"   "4693799"   "4885003"   "4921484"   "4981478"   "5002560"   "5 041093"   "5161427"   "52 03772"   "5245887"   "542 1832"   "5527282"   "5569 184"   "5593550"   "56051 62"   "5693196"   "569546 9"   "5830329"   "5865800"   "5910154"   "5911734"   "5925060"   "5961511"   "5 972019"   "6066158"   "61 46396"   "6245089"   "625 8115"   "6325815").PN.	USP AT	2004/09/2 9 13:44			0